

INVOICE

Invoice No.	Date
000987	11/9/2018
Refer to Invoice Number When Remitting	

Sold To

Moore Twining Associates
2527 Fresno Street
Frenso, CA 93721
USA

Ship To

Moore Twining Associates
5675 Power Inn Rd
Suite C
Sacramento, CA 95824
USA

ATTN: Marshall Hislop

Attn:

Sales Order	Cust No	Customer PO	Order Date	Tax	Mark Shipment	Terms
0010666-0000	102673	Mike Grogan	10/24/2018	T		NET 30
Salesperson	Ship Date	Shipped Via	FOB Point	Ins	Waybill Number	
	11/8/2018				000000440	

Item	T	Quantity			Part Number/Revision	Description	Unit Price \$	Amount \$
		Order	BO	Ship				
002	S	1.00		1.00	S3450	MODEL: 3450 SERIAL #: 535 3450 GAUGE		
003	S	1.00		1.00	102879	Wipe Test Label	1.24	1.24
004	S	1.00		1.00	SERV	CLEANING & MAINTENANCE		
005	S	1.00		1.00	012752	Seal Wiper	3.27	3.27
006	S	1.00		1.00	012754	Ring Scraper	16.15	16.15
007	S	1.00		1.00	102399	Shield Spring 3400	3.02	3.02
008	S	1.00		1.00	102103	Cap Screw Bumper	1.38	1.38
009	S	2.00		2.00	SERV	3BLK CALIBRATION	105.00	210.00
010	S	2.00		2.00	106444.7000	Label, Dot Yellow II Cs /	1.92	3.84
011	S	1.00		1.00	102109.3000	Label, Type "A" With Rq(My	2.62	2.62
						SUBTOTAL		241.52
						California .07250		17.52
						SACRAMENTO .01000		2.41
						Tax Subtotal		19.93
						SUBTOTAL		261.45
						Routine Maintenance Winter special		
						Total \$		261.45

Troxler Electronic Laboratories, Inc.
3008 East Cornwallis Rd,
Research Triangle Park, NC USA

Phone: 1.877.TROXLER (876.9537)
Outside USA : +1.919.549.8661
Fax: +1.919.549.0761

Website: www.troxlerlabs.com