

| Model | Serial # | Qty, TBq | Ship Date  | Company                  | Country   |
|-------|----------|----------|------------|--------------------------|-----------|
| 3430  | 78727    | 1.48E-03 | 1/15/2021  | Geo-Con Products Pty Co. | Australia |
| 3440  | 78728    | 1.48E-03 | 1/15/2021  | Geo-Con Products Pty Co. | Australia |
| 3440  | 78485    | 1.48E-03 | 1/22/2021  | Vtech Materials Testing  | Australia |
| 3440  | 78716    | 1.48E-03 | 1/22/2021  | Vtech Materials Testing  | Australia |
| 3440  | 78758    | 1.48E-03 | 1/22/2021  | Vtech Materials Testing  | Australia |
| 3440  | 78759    | 1.48E-03 | 1/22/2021  | Vtech Materials Testing  | Australia |
| 3440  | 78760    | 1.48E-03 | 1/22/2021  | Vtech Materials Testing  | Australia |
| 3440  | 766702   | 1.48E-03 | 2/24/2021  | Vtech Materials Testing  | Australia |
| 3440  | 766703   | 1.48E-03 | 2/24/2021  | Vtech Materials Testing  | Australia |
| 3440  | 766704   | 1.48E-03 | 2/24/2021  | Vtech Materials Testing  | Australia |
| 3440  | 766705   | 1.48E-03 | 2/24/2021  | Vtech Materials Testing  | Australia |
| 3440  | 766706   | 1.48E-03 | 2/24/2021  | Vtech Materials Testing  | Australia |
| 3430  | 79319    | 1.48E-03 | 6/11/2021  | Vtech Materials Testing  | Australia |
| 3430  | 79320    | 1.48E-03 | 6/11/2021  | Vtech Materials Testing  | Australia |
| 3440  | 79321    | 1.48E-03 | 6/11/2021  | Vtech Materials Testing  | Australia |
| 3440  | 79322    | 1.48E-03 | 6/11/2021  | Vtech Materials Testing  | Australia |
| 3440  | 79323    | 1.48E-03 | 6/11/2021  | Vtech Materials Testing  | Australia |
| 3430  | 79565    | 1.48E-03 | 8/4/2021   | Vtech Materials Testing  | Australia |
| 3430  | 79566    | 1.48E-03 | 8/4/2021   | Vtech Materials Testing  | Australia |
| 3430  | 79567    | 1.48E-03 | 8/4/2021   | Vtech Materials Testing  | Australia |
| 3440  | 79569    | 1.48E-03 | 8/4/2021   | Vtech Materials Testing  | Australia |
| 3440  | 79570    | 1.48E-03 | 8/4/2021   | Vtech Materials Testing  | Australia |
| 3430  | 79845    | 1.48E-03 | 9/22/2021  | Vtech Materials Testing  | Australia |
| 3430  | 79846    | 1.48E-03 | 9/22/2021  | Vtech Materials Testing  | Australia |
| 3430  | 79847    | 1.48E-03 | 9/22/2021  | Vtech Materials Testing  | Australia |
| 3440  | 79848    | 1.48E-03 | 9/22/2021  | Vtech Materials Testing  | Australia |
| 3430  | 80000    | 1.48E-03 | 9/29/2021  | Vtech Materials Testing  | Australia |
| 3430  | 80001    | 1.48E-03 | 9/29/2021  | Vtech Materials Testing  | Australia |
| 3430  | 80002    | 1.48E-03 | 9/29/2021  | Vtech Materials Testing  | Australia |
| 3440  | 80003    | 1.48E-03 | 9/29/2021  | Vtech Materials Testing  | Australia |
| 3440  | 80004    | 1.48E-03 | 9/29/2021  | Vtech Materials Testing  | Australia |
| 3430  | 80024    | 1.48E-03 | 10/28/2021 | Vtech Materials Testing  | Australia |

| Model | Serial # | Qty, TBq | Ship Date  | Company                  | Country   |
|-------|----------|----------|------------|--------------------------|-----------|
| 3430  | 80025    | 1.48E-03 | 10/28/2021 | Vtech Materials Testing  | Australia |
| 3440  | 80026    | 1.48E-03 | 10/28/2021 | Vtech Materials Testing  | Australia |
| 3440  | 80027    | 1.48E-03 | 10/28/2021 | Vtech Materials Testing  | Australia |
| 3440  | 80028    | 1.48E-03 | 10/28/2021 | Vtech Materials Testing  | Australia |
| 3430  | 80190    | 1.48E-03 | 12/7/2021  | Vtech Materials Testing  | Australia |
| 3430  | 80196    | 1.48E-03 | 12/7/2021  | Vtech Materials Testing  | Australia |
| 3440  | 80197    | 1.48E-03 | 12/7/2021  | Vtech Materials Testing  | Australia |
| 3440  | 80199    | 1.48E-03 | 12/7/2021  | Vtech Materials Testing  | Australia |
| 3440  | 80130    | 1.48E-03 | 10/26/2021 | CHAMMAS ENGENHARIA LTDA. | Brazil    |
| 3440  | 80131    | 1.48E-03 | 10/26/2021 | CHAMMAS ENGENHARIA LTDA. | Brazil    |
| 3440  | 80132    | 1.48E-03 | 10/26/2021 | CHAMMAS ENGENHARIA LTDA. | Brazil    |
| 3430  | 79254    | 1.48E-03 | 5/20/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79271    | 1.48E-03 | 5/20/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3440  | 79254    | 1.48E-03 | 5/20/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3440  | 79271    | 1.48E-03 | 5/20/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79233    | 1.48E-03 | 5/20/2021  | Hermie Manalo Consulting | Canada    |
| 3430  | 79234    | 1.48E-03 | 5/20/2021  | Hermie Manalo Consulting | Canada    |
| 3430  | 79253    | 1.48E-03 | 5/20/2021  | Hermie Manalo Consulting | Canada    |
| 3440  | 79233    | 1.48E-03 | 5/20/2021  | Hermie Manalo Consulting | Canada    |
| 3440  | 79234    | 1.48E-03 | 5/20/2021  | Hermie Manalo Consulting | Canada    |
| 3440  | 79253    | 1.48E-03 | 5/20/2021  | Hermie Manalo Consulting | Canada    |
| 3430  | 79367    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79368    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79396    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79397    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79398    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79399    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79400    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79401    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79402    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3430  | 79403    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |
| 3440  | 79367    | 1.48E-03 | 5/28/2021  | 879142 Ab Ltd O/A Measur | Canada    |

| Model | Serial # | Qty, TBq | Ship Date | Company                  | Country |
|-------|----------|----------|-----------|--------------------------|---------|
| 3440  | 79368    | 1.48E-03 | 5/28/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79396    | 1.48E-03 | 5/28/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79397    | 1.48E-03 | 5/28/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79398    | 1.48E-03 | 5/28/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79399    | 1.48E-03 | 5/28/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79400    | 1.48E-03 | 5/28/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79401    | 1.48E-03 | 5/28/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79402    | 1.48E-03 | 5/28/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79403    | 1.48E-03 | 5/28/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3430  | 79583    | 1.48E-03 | 6/25/2021 | BDT Engineering          | Canada  |
| 3440  | 79583    | 1.48E-03 | 6/25/2021 | BDT Engineering          | Canada  |
| 3430  | 79579    | 1.48E-03 | 6/25/2021 | Peter Kiewit Sons ULC    | Canada  |
| 3430  | 79585    | 1.48E-03 | 6/25/2021 | Peter Kiewit Sons ULC    | Canada  |
| 3440  | 79579    | 1.48E-03 | 6/25/2021 | Peter Kiewit Sons ULC    | Canada  |
| 3440  | 79585    | 1.48E-03 | 6/25/2021 | Peter Kiewit Sons ULC    | Canada  |
| 3430  | 79589    | 1.48E-03 | 6/25/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3430  | 79591    | 1.48E-03 | 6/25/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79589    | 1.48E-03 | 6/25/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79591    | 1.48E-03 | 6/25/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3430  | 79575    | 1.48E-03 | 6/28/2021 | McIntosh And Lalani      | Canada  |
| 3430  | 79580    | 1.48E-03 | 6/28/2021 | McIntosh And Lalani      | Canada  |
| 3430  | 79586    | 1.48E-03 | 6/28/2021 | McIntosh And Lalani      | Canada  |
| 3440  | 79575    | 1.48E-03 | 6/28/2021 | McIntosh And Lalani      | Canada  |
| 3440  | 79580    | 1.48E-03 | 6/28/2021 | McIntosh And Lalani      | Canada  |
| 3440  | 79586    | 1.48E-03 | 6/28/2021 | McIntosh And Lalani      | Canada  |
| 3430  | 79577    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |
| 3430  | 79582    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |
| 3430  | 79584    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |
| 3430  | 79587    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |
| 3430  | 79590    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |
| 3440  | 79577    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |
| 3440  | 79582    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |

| Model | Serial # | Qty, TBq | Ship Date | Company                  | Country |
|-------|----------|----------|-----------|--------------------------|---------|
| 3440  | 79584    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |
| 3440  | 79587    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |
| 3440  | 79590    | 1.48E-03 | 6/28/2021 | Inline Equipment         | Canada  |
| 3440  | 79626    | 1.48E-03 | 6/29/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3440  | 79627    | 1.48E-03 | 6/29/2021 | 879142 Ab Ltd O/A Measur | Canada  |
| 3430  | 78840    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3430  | 78841    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3430  | 78842    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3430  | 78843    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3430  | 78844    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3440  | 78840    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3440  | 78841    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3440  | 78842    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3440  | 78843    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3440  | 78844    | 1.48E-03 | 2/11/2021 | Troxservice Sa           | Chile   |
| 3430  | 79125    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3430  | 79126    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3430  | 79127    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3430  | 79128    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3430  | 79129    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3440  | 79125    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3440  | 79126    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3440  | 79127    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3440  | 79128    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3440  | 79129    | 1.48E-03 | 4/7/2021  | Troxservice Sa           | Chile   |
| 3430  | 79641    | 1.48E-03 | 8/4/2021  | Troxservice Sa           | Chile   |
| 3430  | 79642    | 1.48E-03 | 8/4/2021  | Troxservice Sa           | Chile   |
| 3430  | 79643    | 1.48E-03 | 8/4/2021  | Troxservice Sa           | Chile   |
| 3430  | 79644    | 1.48E-03 | 8/4/2021  | Troxservice Sa           | Chile   |
| 3430  | 79645    | 1.48E-03 | 8/4/2021  | Troxservice Sa           | Chile   |
| 3440  | 79641    | 1.48E-03 | 8/4/2021  | Troxservice Sa           | Chile   |
| 3440  | 79642    | 1.48E-03 | 8/4/2021  | Troxservice Sa           | Chile   |

| Model | Serial # | Qty, TBq | Ship Date  | Company        | Country |
|-------|----------|----------|------------|----------------|---------|
| 3440  | 79643    | 1.48E-03 | 8/4/2021   | Troxservice Sa | Chile   |
| 3440  | 79644    | 1.48E-03 | 8/4/2021   | Troxservice Sa | Chile   |
| 3440  | 79645    | 1.48E-03 | 8/4/2021   | Troxservice Sa | Chile   |
| 3430  | 79840    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3430  | 79841    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3430  | 79842    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3430  | 79843    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3430  | 79844    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3440  | 79840    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3440  | 79841    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3440  | 79842    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3440  | 79843    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3440  | 79844    | 1.48E-03 | 9/3/2021   | Troxservice Sa | Chile   |
| 3430  | 80074    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3430  | 80075    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3430  | 80076    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3430  | 80077    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3430  | 80078    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3440  | 80074    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3440  | 80075    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3440  | 80076    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3440  | 80077    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3440  | 80078    | 1.48E-03 | 10/22/2021 | Troxservice Sa | Chile   |
| 3430  | 80226    | 1.48E-03 | 11/24/2021 | Troxservice Sa | Chile   |
| 3430  | 80227    | 1.48E-03 | 11/24/2021 | Troxservice Sa | Chile   |
| 3430  | 80228    | 1.48E-03 | 11/24/2021 | Troxservice Sa | Chile   |
| 3430  | 80229    | 1.48E-03 | 11/24/2021 | Troxservice Sa | Chile   |
| 3430  | 80230    | 1.48E-03 | 11/24/2021 | Troxservice Sa | Chile   |
| 3440  | 80226    | 1.48E-03 | 11/24/2021 | Troxservice Sa | Chile   |
| 3440  | 80227    | 1.48E-03 | 11/24/2021 | Troxservice Sa | Chile   |
| 3440  | 80228    | 1.48E-03 | 11/24/2021 | Troxservice Sa | Chile   |
| 3440  | 80229    | 1.48E-03 | 11/24/2021 | Troxservice Sa | Chile   |

| Model | Serial # | Qty, TBq | Ship Date  | Company                        | Country            |
|-------|----------|----------|------------|--------------------------------|--------------------|
| 3440  | 80230    | 1.48E-03 | 11/24/2021 | Troxservice Sa                 | Chile              |
| 3430  | 76429    | 1.48E-03 | 1/14/2021  | The Lab (Asia) Ltd.            | China              |
| 3430  | 76430    | 1.48E-03 | 1/14/2021  | The Lab (Asia) Ltd.            | China              |
| 3440  | 76429    | 1.48E-03 | 1/14/2021  | The Lab (Asia) Ltd.            | China              |
| 3440  | 76430    | 1.48E-03 | 1/14/2021  | The Lab (Asia) Ltd.            | China              |
| 3440  | 79495    | 1.48E-03 | 6/18/2021  | FT Laboratories Ltd            | China              |
| 3440  | 79496    | 1.48E-03 | 6/18/2021  | FT Laboratories Ltd            | China              |
| 3440  | 79497    | 1.48E-03 | 6/18/2021  | FT Laboratories Ltd            | China              |
| 3430  | 80377    | 1.48E-03 | 12/21/2021 | Dirimpex SAS                   | Colombia           |
| 3440  | 80377    | 1.48E-03 | 12/21/2021 | Dirimpex SAS                   | Colombia           |
| 3430  | 78792    | 1.48E-03 | 1/20/2021  | Indarca                        | Dominican Republic |
| 3430  | 79215    | 1.48E-03 | 5/21/2021  | Lindqvist Int'L S.A.           | France             |
| 3430  | 79216    | 1.48E-03 | 5/21/2021  | Lindqvist Int'L S.A.           | France             |
| 3440  | 79217    | 1.48E-03 | 5/21/2021  | Lindqvist Int'L S.A.           | France             |
| 3440  | 79218    | 1.48E-03 | 5/21/2021  | Lindqvist Int'L S.A.           | France             |
| 3440  | 79219    | 1.48E-03 | 5/21/2021  | Lindqvist Int'L S.A.           | France             |
| 3440  | 79428    | 1.48E-03 | 6/24/2021  | Lindqvist Int'L S.A.           | France             |
| 3440  | 79429    | 1.48E-03 | 6/24/2021  | Lindqvist Int'L S.A.           | France             |
| 3450  | 79430    | 1.48E-03 | 6/24/2021  | Lindqvist Int'L S.A.           | France             |
| 3450  | 79431    | 1.48E-03 | 6/24/2021  | Lindqvist Int'L S.A.           | France             |
| 3450  | 79432    | 1.48E-03 | 6/24/2021  | Lindqvist Int'L S.A.           | France             |
| 3430  | 79158    | 1.48E-03 | 4/22/2021  | Groundtest Equipment           | New Zealand        |
| 3430  | 79159    | 1.48E-03 | 4/22/2021  | Groundtest Equipment           | New Zealand        |
| 3430  | 79160    | 1.48E-03 | 4/22/2021  | Groundtest Equipment           | New Zealand        |
| 3440  | 79518    | 1.48E-03 | 6/29/2021  | Groundtest Equipment           | New Zealand        |
| 3440  | 79519    | 1.48E-03 | 6/29/2021  | Groundtest Equipment           | New Zealand        |
| 3430  | 79088    | 1.48E-03 | 4/30/2021  | LAMSA Ingenieros Consultores   | Nicaragua          |
| 3430  | 79089    | 1.48E-03 | 4/30/2021  | LAMSA Ingenieros Consultores   | Nicaragua          |
| 3440  | 79088    | 1.48E-03 | 4/30/2021  | LAMSA Ingenieros Consultores   | Nicaragua          |
| 3440  | 79089    | 1.48E-03 | 4/30/2021  | LAMSA Ingenieros Consultores   | Nicaragua          |
| 3440  | 79965    | 1.48E-03 | 9/21/2021  | Global Supply de Nicaragua,S.A | Nicaragua          |
| 3440  | 78917    | 1.48E-03 | 2/16/2021  | First Balfour Inc.             | Philippines        |

| Model | Serial # | Qty, TBq | Ship Date  | Company                       | Country                      |
|-------|----------|----------|------------|-------------------------------|------------------------------|
| 3440  | 79284    | 1.48E-03 | 5/14/2021  | First Balfour Inc.            | Philippines                  |
| 3440  | 79285    | 1.48E-03 | 10/22/2021 | EC De Luna Construction Corp. | Philippines                  |
| 3440  | 79311    | 1.48E-03 | 10/22/2021 | EC De Luna Construction Corp. | Philippines                  |
| 3440  | 1125     | 1.48E-03 | 11/4/2021  | Daewoo Eng. & Const. Co, Ltd  | Philippines                  |
| 3440  | 1126     | 1.48E-03 | 11/4/2021  | Daewoo Eng. & Const. Co, Ltd  | Philippines                  |
| 3440  | 80220    | 1.48E-03 | 11/4/2021  | Daewoo Eng. & Const. Co, Ltd  | Philippines                  |
| 3430  | 78835    | 1.48E-03 | 2/12/2021  | ATECO Saudi Arabia            | Saudi Arabia                 |
| 3440  | 79648    | 1.48E-03 | 7/22/2021  | Acender Technology Pte Ltd    | Singapore                    |
| 3440  | 79649    | 1.48E-03 | 7/22/2021  | Acender Technology Pte Ltd    | Singapore                    |
| 3440  | 80180    | 1.48E-03 | 10/28/2021 | Acender Technology Pte Ltd    | Singapore                    |
| 3430  | 78816    | 1.48E-03 | 2/9/2021   | V.I. Instruments              | South Africa                 |
| 3430  | 78817    | 1.48E-03 | 2/9/2021   | V.I. Instruments              | South Africa                 |
| 3430  | 78818    | 1.48E-03 | 2/9/2021   | V.I. Instruments              | South Africa                 |
| 3430  | 78819    | 1.48E-03 | 2/9/2021   | V.I. Instruments              | South Africa                 |
| 3430  | 78820    | 1.48E-03 | 2/9/2021   | V.I. Instruments              | South Africa                 |
| 3440  | 78821    | 1.48E-03 | 2/9/2021   | V.I. Instruments              | South Africa                 |
| 3440  | 78822    | 1.48E-03 | 2/9/2021   | V.I. Instruments              | South Africa                 |
| 3450  | 78825    | 1.48E-03 | 2/9/2021   | V.I. Instruments              | South Africa                 |
| 3430  | 79453    | 1.48E-03 | 8/16/2021  | V.I. Instruments              | South Africa                 |
| 3430  | 79471    | 1.48E-03 | 8/16/2021  | V.I. Instruments              | South Africa                 |
| 3430  | 79476    | 1.48E-03 | 8/16/2021  | V.I. Instruments              | South Africa                 |
| 3430  | 79687    | 1.48E-03 | 8/24/2021  | V.I. Instruments              | South Africa                 |
| 3430  | 79688    | 1.48E-03 | 8/24/2021  | V.I. Instruments              | South Africa                 |
| 3430  | 79689    | 1.48E-03 | 8/24/2021  | V.I. Instruments              | South Africa                 |
| 3430  | 80050    | 1.48E-03 | 10/22/2021 | V.I. Instruments              | South Africa                 |
| 3430  | 80059    | 1.48E-03 | 10/22/2021 | V.I. Instruments              | South Africa                 |
| 3440  | 80050    | 1.48E-03 | 10/22/2021 | V.I. Instruments              | South Africa                 |
| 3440  | 80059    | 1.48E-03 | 10/22/2021 | V.I. Instruments              | South Africa                 |
| 3440  | 79650    | 1.48E-03 | 9/8/2021   | Mecanica Cientifica S.A.      | Spain                        |
| 3440  | 78676    | 1.48E-03 | 1/7/2021   | Tanzania New Wami Bridge      | Tanzania, United Republic of |
| 3440  | 78677    | 1.48E-03 | 1/7/2021   | Tanzania New Wami Bridge      | Tanzania, United Republic of |
| 3440  | 79070    | 1.48E-03 | 5/19/2021  | CHN Henan Int'l Coop Grp      | Tanzania, United Republic of |

| Model | Serial # | Qty, TBq | Ship Date  | Company                        | Country                      |
|-------|----------|----------|------------|--------------------------------|------------------------------|
| 3440  | 79433    | 1.48E-03 | 6/10/2021  | YAPI MERKEZI INSAAT V.S.A.S.   | Tanzania, United Republic of |
| 3440  | 79434    | 1.48E-03 | 6/10/2021  | YAPI MERKEZI INSAAT V.S.A.S.   | Tanzania, United Republic of |
| 3440  | 79435    | 1.48E-03 | 6/10/2021  | YAPI MERKEZI INSAAT V.S.A.S.   | Tanzania, United Republic of |
| 3440  | 79036    | 1.48E-03 | 6/14/2021  | SINOHYDRO CORPORATION LTD      | Tanzania, United Republic of |
| 3430  | 79447    | 1.48E-03 | 8/16/2021  | China Railway Seventh Group    | Tanzania, United Republic of |
| 3430  | 79448    | 1.48E-03 | 8/16/2021  | China Railway Seventh Group    | Tanzania, United Republic of |
| 3440  | 79194    | 1.48E-03 | 4/29/2021  | Asia Testing Equipment         | Thailand                     |
| 3440  | 79195    | 1.48E-03 | 4/29/2021  | Asia Testing Equipment         | Thailand                     |
| 3440  | 79573    | 1.48E-03 | 7/6/2021   | CFU ULUSL.DIS TIC.VE SERV.HIZM | Turkey                       |
| 3450  | 79086    | 1.48E-03 | 4/9/2021   | GULSAN INSAAT SANAYI TURIZM    | Uganda                       |
| 3450  | 79087    | 1.48E-03 | 4/9/2021   | GULSAN INSAAT SANAYI TURIZM    | Uganda                       |
| 3440  | 79131    | 1.48E-03 | 4/29/2021  | Controls Testing Equip.        | United Kingdom               |
| 3430  | 78979    | 1.48E-03 | 8/13/2021  | Controls Testing Equip.        | United Kingdom               |
| 3430  | 78980    | 1.48E-03 | 8/13/2021  | Controls Testing Equip.        | United Kingdom               |
| 3430  | 78981    | 1.48E-03 | 8/13/2021  | Controls Testing Equip.        | United Kingdom               |
| 3430  | 78982    | 1.48E-03 | 8/13/2021  | Controls Testing Equip.        | United Kingdom               |
| 3440  | 78979    | 1.48E-03 | 8/13/2021  | Controls Testing Equip.        | United Kingdom               |
| 3440  | 78980    | 1.48E-03 | 8/13/2021  | Controls Testing Equip.        | United Kingdom               |
| 3440  | 78981    | 1.48E-03 | 8/13/2021  | Controls Testing Equip.        | United Kingdom               |
| 3440  | 78982    | 1.48E-03 | 8/13/2021  | Controls Testing Equip.        | United Kingdom               |
| 3440  | 80223    | 1.48E-03 | 11/18/2021 | Controls Testing Equip.        | United Kingdom               |
| 3440  | 80224    | 1.48E-03 | 11/18/2021 | Controls Testing Equip.        | United Kingdom               |